

Determination D0109EN	Edition: 10	Owner: PEQAC	Everllence
	Valid from: 2026-01-26		
	Review: 2029-04-17		
Approval List LO for Distillate Fuel Operation SAE 40			

Applicable for Everllence four stroke medium-speed large bore engines (type 32/40, 32/44, 35/44, 48/60, 49/60, 51/60) and for all engines of the Pielstick brand except PA4 200 ID engines

Company	Oil Brand	BASE NUMBER (mg KOH/g)
Castrol	MLC 40	12
	MHP 154	15
	MHP 1-40	12
Chevron (Texaco, Caltex)	Delo 1000 Marine 40	12
	Delo SHP40	12
	Taro 12 XP 40 / Taro 12 XP 40 (2)	12
	Taro 16 XP 40 / Taro 16 XP 40 (2)	16
	Delo 400 TBN10*	10
	HDAX 9700 SAE 40**	5.8
ExxonMobil	Mobilgard 412 (Gp1) / Mobilgard 412 (Gp2)	15
	Mobilgard 1SHC	15.6
	Mobilgard ADL 40 (Gp1) / Mobilgard ADL 40 (Gp2)	12
	Mobil Delvac 1640 (Gp1) / Mobil Delvac 1640 (Gp2)	12
Fuchs Petrolube	Fuchs Titan MarWay 1040*	10.6
Gulf Oil Marine	GulfSea Power MDO 4012S	12
	GulfSea Power MDO 4015S	15

We do not assume any responsibility for difficulties that might be caused by these oils.

For Pielstick engines, not all recommended lube oils are listed in this document. For more information, please contact your Pielstick technical correspondent.

*** Sulfur content in fuel max. 1% (10 000 ppm)**

**** Sulfur content in fuel max. 0.1% (1 000 ppm)**

Determination	Edition: 10	Owner:	Everllence
	Valid from: 2026-01-26	PEQAC	
D0109EN	Review: 2029-04-17		
Approval List LO for Distillate Fuel Operation SAE 40			

Applicable for Everllence four stroke medium-speed large bore engines (type 32/40, 32/44, 35/44, 48/60, 49/60, 51/60) and for all engines of the Pielstick brand except PA4 200 ID engines

Company	Brand	BASE NUMBER (mg KOH/g)
Shell	Gadina AL 40	15
	Gadina S3	12
	Gadina S4	15
	Sirius X40	17
Sinopec	Marine TPEO 4012	13.3
	Marine TPEO 4015	15
SK Lubricants	Supermar 13TP40	13
	Supermar 15TP40	15
TotalEnergies	Disola M 4015	15
	Disola M 4012	12
	Disola 4015	15
	Disola 4012	12
	Caprano M 40	14
	Caprano 4015	15
	Caprano 4012	12
Vibra Energia	Marbrax CCD-410	12
	Marbrax CCD-415	15
	Lubrux Marine TP 1-40	12

We do not assume any responsibility for difficulties that might be caused by these oils.
For Pielstick engines, not all recommended lube oils are listed in this document. For more information, please contact your Pielstick technical correspondent.