


Action code: WHEN CONVENIENT

**Update of fuel valve opening pressure**SL2024-753/JNN  
March 2024**Concerns**Owners and operators of  
MAN four-stroke engines.

Type:

Marine: L27/38

Stationary: L27/38S

**Attachment:**D50035-110  
.....

Dear Sir or Madam

We have decided to reduce the setting value for the opening pressure of the injection nozzle as shown in description D50035-110.

By reducing the opening pressure, we can improve the lifetime of the injection nozzles. The readjustment of the opening pressure does not require adjustment of other parameters on the engine.

Please insert the updated description D50035-110 in your Instruction Manual and discard the previous version.

For further information concerning the content of this Service Letter, please contact your local PrimeServ agent or our PrimeServ department by e-mail to: [primeserv-hol@man-es.com](mailto:primeserv-hol@man-es.com)

Yours faithfully

**Susanne Kindt**  
Vice President  
Engineering**Lars Danefeld Søndersby**  
Senior Manager,  
Production Support